

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 51 52 56  
 0 1 P A T M I 2 0 0 0 - 0 0 0 0 0 0 - 0 0 0 4 1 1 1 1 1 1 4 5  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE JO CAT SF

7 8 60 61 68 69 74 75 80 81  
 0 1 REPORT SOURCE L 6 0 5 0 0 0 0 3 2 0 7 0 4 2 8 7 9 8 0 1 1 1 5 8 0 9  
 DOCKET NUMBER EVENT DATE REPORT DATE

7 8 9 80  
 0 2 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
 Fire pump FS-P2 had been restored to service but successful surveillance testing  
 0 3 was not completed until May 5, 1979. An overheating problem which required  
 0 4 rebuilding of the FS-P3 diesel occurred while FS-P2 was not available for use,  
 0 5 During the one day period with only two fire pumps available, MI-II fire pump  
 0 6 FS-P1 overheated and was off line for a three hour period. With only one fire pump  
 0 7 available, temporary measures were considered but not taken since FS-P1 was restored  
 0 8 to operable status in three hours and FS-P2 was made available (continuing)  
 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49  
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
 A R D X P U M P X Y Z  
 LEH NO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO  
 7 9  
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFRD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
 Z Z Z 0 0 0 0 N N

7 8 9 80  
 1 0 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
 This event occurred as the result of system leakage in excess of the jockey pump's  
 1 1 capacity which resulted in the diesel driven fire pumps running continuously.  
 1 2 A cooling system reservoir was added to FS-P3 but determined not to be needed on  
 1 3 FS-P1 (Unit 2). OP 7104-0.1 (Unit 2) and O.P. 1104-45 (Unit 1) have been revised  
 1 4 to require operator attendance during diesel runs and to outline newly (Continuing)  
 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49  
 FACILITY STATUS POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
 G 0 0 0 NA B Operator Observation

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49  
 ACTIVITY CONTENT AMOUNT OF ACTIVITY LOCATION OF RELEASE  
 Z Z NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49  
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
 0 0 0 NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49  
 PERSONNEL INJURIES NUMBER DESCRIPTION  
 0 0 0 NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49  
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
 Z NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49  
 PUBLICITY STATUS DESCRIPTION  
 Y NA

*A002  
S  
1/1*

January 15, 1980

LER 79-016/03L-0

Event Description and Probably Consequences: (10)

with untested capacity. This is considered reportable under T.S. 6.9.1, equipment failure as described in T.S. action statement 3.7.10.

Cause Description and Corrective Actions: (27)

developed cooldown procedures at the termination of each run. The Unit II diesel driven pump (FS-P1) overheating was the result of several intermittent runs to raise system pressure with no cooldown performed between runs. Full operational status was restored on May 5, 1979 for all four fire pumps which is within the action statement requirements of T.S. 3.7.10.