

JUN 15 1983

0



GPU Nuclear Corporation  
Post Office Box 480  
Route 441 South  
Middletown, Pennsylvania 17057  
717 944-7621  
TELEX 84-2386  
Writer's Direct Dial Number:

May 19, 1983  
4410-83-L-0082

80-057

Office of Inspection and Enforcement  
Attn: Mr. J. M. Allan  
Acting Regional Administrator  
Region I  
US Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406


Dear Sir:

Three Mile Island Nuclear Station, Unit 2 (TMI-2)  
Operating License No. DPR-73  
Docket No. 50-320  
Updated Licensee Event Reports

The Licensee Event Reports listed in Attachment 1 have been updated and are enclosed as Attachment 2 to this letter.

If you have any questions, please contact Mr. J. J. Byrne of my staff.

Sincerely,

  
B. K. Kanga  
Director, TMI-2

BKK/RDW/jep

Attachments

CC: Mr. L. H. Barrett, Deputy Program Director - TMI Program Office  
Dr. B. J. Snyder, Program Director - TMI Program Office

8305310001 830519  
PDR ADCK 05000320  
S PDR

IE22

LIST OF UPDATED LICENSEE EVENT REPORTS

<u>LER NO.</u>	<u>LER NO.</u>
80-01	81-12
80-05	81-20
80-07	81-22
80-12	81-23
80-49	81-32
80-54	81-34
80-55	81-35
80-56	81-36
80-57	81-38
81-04 *	82-34
81-08	
81-10	

\* Event date on original Licensee Event Report was incorrect. This revision corrects the event date.



LINCESEE EVENT REPORT  
NARRATIVE REPORT  
TMI-II  
LER 80-057/03X-1  
EVENT DATE - December 17, 1980

I. EXPLANATION OF OCCURRENCE

On December 17th, during performance of Surveillance Procedure 4303-M10, entitled "Chlorine Detector System," the air intake tunnel chlorine monitor was found to be inoperable in that when the probe was exposed to chlorine vapors the monitor did not respond. The Chlorine Detector System, required operable by Technical Specification 3.3.3.7, was declared inoperable. The probe was cleaned and the Chlorine Detector System returned to an operable status by successfully completing the surveillance requirements. Full implementation of the action statement requirements was not necessary as the monitor was returned to service within an hour.

This event is not a violation of Technical Specification 3.3.3.7, but is reported under Section 6.9.1.9(b) as the action statement was entered inadvertently.

II. CAUSE OF THE OCCURRENCE

The cause of this event was that the probe had become dirty. This reduced its sensitivity to detect chlorine at the required level.

III. CIRCUMSTANCES SURROUNDING THE OCCURRENCE

At the time of the occurrence, the Unit II facility was in a long term cold shutdown state. The reactor decay heat was being removed via natural circulation to the A steam generator which is operating in a 'steaming' mode. Throughout the event there was no Loss of Natural Circulation heat removal in the RCS system.

IV. CORRECTIVE ACTIONS TAKEN OR TO BE TAKEN

IMMEDIATE

The probe was removed from service, cleaned, and returned to service by reperforming the surveillance test successfully.

LONG TERM

Surveillance procedure 4303-M10 was revised on September 8, 1980, to increase the cleaning frequency of the probe to once per 31 days.

V. COMPONENT FAILURE DATA

Electrode Assemblies for Model 17E1100 DETECTACHLOR, Chlorine Gas Detector System manufactured by: Fischer & Porter Co.