

Metropolitan Edison Company Post Office Box 480 Middletown, Pennsylvania 17057

Writer's Direct Dial Number

March 5, 1981 LL2-81-0064

Office of Inspection and Enforcement Attn: Mr. Boyce H. Grier, Director Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit 2 (TMI-2)
Operating License No. DPR-73
Docket No. 50-320
Licensee Event Report 81-03/03L-0

Attached please find Licensee Event Report 81-03/03L-0 concerning the Fire Protection System Deluge Valve FS-V-426A failure on February 2, 1981.

This event concerns Section 3.7.10.2 and is considered reportable under Section 6.9.1.9 of the Interim Recovery Technical Specifications.

This LER is being submitted one day late as discussed on February 4, 1981 by our Mr. S. D. Chaplin of the Licensing department with Mr. R. J. Conte, Senior Resident Inspector, TMI Program Office, U. S. NRC.

Sincerely,

/s/G. K. Hovey

G. K. Hovey Vice-President and Director, TMI-2

CKH:SDC:djb

Attachments

cc: L. Barrett, Deputy Program Director
Dr. B. J. Snyder, Program Director, TMI Office

f1007

8103120631

S

Metropolitan Edison Company is a Member of the General Public Utilities System

LICENSEE EVENT REPORT

LL2-81-0064

	Attachment 1 CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
	P A T M I 2 2 0 0 - 0 0 0 - 0 0 3 4 1 1 1 4
CON'T	9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
0 1	HEPORT L 6 0 5 0 0 3 2 0 7 0 2 0 2 8 1 8 0 3 0 5 8 1 9
0 2	At 1145 hours on February 2nd, while performing surveillance 4333-R2, deluge valve
03	FS-V-426A failed to operate properly. Manual actuation capability was confirmed and
0 4	a roving fire watch implemented.
0 5	This is not a violation of any Tech. Spec., it is reportable under section 6.9.1.9(b)
0 6	due to inadvertent entry into the action statement of section 3.7.10.2. This event
0 7	had no effect on the plant, its operation, or the health and safety of the public.
08	9 SYSTEM CAUSE CAUSE OF COMP VALVE
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE TAKEN ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER B 18 Z 19 Z 20 Z 21 0 0 0 0 0 0 Y 23 N 24 A 25 S 2 1 2 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0	The solenoid was dismantled but there was no apparent cause for the malfunction. The
11	parts were cleaned and reassembled. Subsequent testing showed the operator to be
1 2	functioning properly. The operator was reinstalled and the system returned to
1 3	an operable status.
1 4 7 8	80
	FACILITY STATUS SPOWER OTHER STATUS OTHER ST
	ACTIVITY CONTENT SELEASED OF RELEASE AMOUNT OF ACTIVITY 36 N/A N/A N/A N/A 80
1 7	PERSONNEL EXPOSURES NUMBER O O O O O O O O O O O O O O O O O O O
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	0 0 0 40 N/A 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	Z 42 N/A
, 8	9 10 PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY N/A
الله 108	N/A 9 10 68 69 80 3 12 0 68 69 80 Steven D. Chaplin BHONE. (717) 948-8461

LICENSEE EVENT REPORT NARRATIVE REPORT TMI-II LER 81-003/03L-0 EVENT DATE - February 02, 1981

I. EXPLANATION OF OCCURRENCE

At 1145 hours on February 2nd, while performing surveillance 4333-R2, "Fire System Deluge/Sprinkler System Functional Test," deluge valve FS-V-426A failed to operate properly. When its associated heat detector was tripped the appropriate alarms were received, but the deluge valve did not actuate automatically as required.

Subsequent manual actuation of the deluge valve functioned properly upon actuation. Deluge valve FS-V-426A provides fire protection of the Emergency Diesel Generator Air Intake.

This is not a violation of Technical Specifications but this report is submitted because action statement 3.7.10.2 was entered unintentionally.

II. CAUSE OF THE OCCURRENCE

The apparent cause of this event was the malfunction of the valves solenoid operator which arrested the automatic release of the hydraulic lock in the deluge valve.

III. CIRCUMSTANCES SURROUNDING THE OCCURENCE

At the time of the occurrence, the Unit 2 facility was in a long-term cold shutdown state. The reactor decay heat was being removed via loss to ambient. Throughout the event there was no effect on the Reactor Coolant System or the core.

IV. CORRECTIVE ACTIONS TAKEN OR TO BE TAKEN

IMMEDIATE

A roving fire watch to check the affected area hourly was implemented. The manual actuation of the deluge valve was considered adequate for the required backup suppression capability required by Tech. Specs.

The solenoid was dismantled but there was no apparent cause for the malfunction. The parts were cleaned and reassembled. Subsequent testing showed the operator to be functioning properly. The operator was reinstalled and the system returned to an operable status.

LONG TERM

 t_i

N/A

V. COMPONENT FAILURE DATA

Skinner Uniflow Valves Series L 125 V DC Solenoid Valve