

Metropolitan Edison Company Post Office Box 480 Middletown, Pennsylvania 17057

Writer's Direct Dial Number

December 11, 1981 LL2-81-0284

Office of Inspection and Enforcement Attn: Mr. Ronald C. Haynes, Director Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit 2 (TMI-Operating License No. DPR-73 Docket No. 50-320 Licensee Event Report 81-033/01L-0

Attached please find Licensee Event Report 81-033/01L-0 concerning the failure of the "B" OTSG level indicator power supply failure on November 13, 1981.

This event constitutes a violation of Section 3.3.3.6 and is considered reportable under Section 6.9.1.8(b) of the Interim Recovery Technical Specifications.

J./J./Barton Acting Director, TMI-2

JJB:SDC:djb

Attachments

> 8112280410 8112120 PDR ADDCK 05000320 PDR S

1637

(7-77)	LICENSEE EVENT REPORT Attachment 1
• .	CONTROL BLOCK: LL2-81-0284 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	P A T M I 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 HICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 4 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 2 0 7 1 1 1 3 8 1 8 1 2 1 1 1 8 1 9 OURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) At 1530 hours on November 13, 1981, the "B" OTSG level indication failed. After
0 3	determination of the cause, the level indication was restored to operable status by
0 4	2155 hours on November 13, 1981. This event had no effect on the plant, its
0 5	operation, or the health and safety of the public.
0 6	
0 7	
08	9 80
0 9 8	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE I D 11 E 12 A 13 I N S T R U 14 P 15 Z 16 9 10 11 12 12 13 13 18 19 19 20 REVISIONE
	LER/RO REPORT NUMBER SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. NO. O 3 3 3 O 1 O 1 L O
	ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
1 0	Investigation determined that the 12 vdc power supply for the level indication
11	instrument transmitter failed thereby causing loss of level indication. The 12 vdc
1 2	power supply was replaced.
1 3	
7 8	9 80
1 5	FACILITY STATUS % POWER OTHER STATUS 30 MFTHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) \[\begin{array}{c ccccccccccccccccccccccccccccccccccc
1 7	
7 8	PERSONNEL EXPOSURES NUMBER. TYPE DESCRIPTION 39 0 0 0 37 Z 38 N/A
7 8	PERSONNEL EXPOSURES NUMBER. TYPE DESCRIPTION 39
	PERSONNEL EXPOSURES NUMBER. TYPE DESCRIPTION (39) 9 11 12 13 80 NUMBER DESCRIPTION (41) 0 0 0 (40) N/A 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION
1 8	PERSONNEL EXPOSURES NUMBER. TYPE DESCRIPTION (39) 9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 0 0 0 0 (40) 11 12 12 13 80 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 2 (42) N/A 9 10 N/A
1 8 7 8 1 9 7 8	PERSONNEL EXPOSURES NUMBER O O O O O O O O O O O O O O O O O O O

NARRATIVE REPORT TMI-II LER 81-033/01L-0 EVENT DATE - November 13, 1981

I. EXPLANATION OF OCCURRENCE

At 1530 hours on November 13, 1981, the "B" Once Through Steam Generator (OTSG) level indication failed. After determination of the cause, the level indication was restored to operable status by 2155 hours on November 13, 1981.

This is a violation of Section 3.3.3.6 and is considered reportable under Section 6.9.1.8(b) of the Interim Recovery Tech. Specs.

II. CAUSE OF THE OCCURRENCE

Investigation determined that the 12 vdc power supply for the level indication instrument transmitter failed, thereby causing loss of level indication.

III. CIRCUMSTANCES SURROUNDING THE OCCURRENCE

At the time of the occurrence, the Unit 2 facility was in a long-term cold shutdown state. The reactor decay heat was being removed via loss to ambient. Throughout the event there was no effect on the Reactor Coolant System or the core.

IV. CORRECTIVE ACTIONS TAKEN OR TO BE TAKEN

IMMEDIATE

The 12 vdc power supply was replaced.

LONG TERM

None appropriate

V. COMPONENT FAILURE DATA

12 vdc power supply: model B15-1.5

manufacturer - Power One, INc. Camarillo, CA