



**GPU Nuclear**  
 P.O. Box 480  
 Middletown, Pennsylvania 17057  
 717-944-7621  
 Writer's Direct Dial Number:


March 4, 1982  
 4400-82-L-0036

MAR 23 1982

Office of Inspection and Enforcement  
 Attn: Mr. Ronald C. Haynes, Director  
 Region I  
 U. S. Nuclear Regulatory Commission  
 631 Park Avenue  
 King of Prussia, Pennsylvania 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit 2 (TMI-2)  
 Operating License No. DPR-73  
 Docket No. 50-320  
 Licensee Event Report 82-07/03L-0



Attached please find Licensee Event Report 82-07/03L-0 concerning Auxiliary Building Ventilation System low flow conditions on January 20, 1982 and January 25, 1982.

These events concern Section 3.9.12 and are considered reportable under Section 6.9.1.9(b) of the Interim Recovery Technical Specifications.

This LER is being submitted after the thirty (30) day Tech Spec requirement as discussed by Mr. S. D. Chaplin of TMI-2 Licensing and Mr. R. J. Conte, Senior Resident Inspector (TMI-2), U. S. Nuclear Regulatory Commission on February 19, 1982.

Sincerely,

J. J. Barton  
 Acting Director, TMI-2

JJB:SDC:djb

Attachments

cc: L. H. Barrett, Deputy Program Director, TMI Program Office  
 Dr. B. J. Snyder, Program Director, TMI Program Office  
 Mr. V. Stello, Deputy Executive Director  
 Operations & Generic Requirements  
 U. S. Nuclear Regulatory Commission  
 Washington, D.C. 20555

8203170558 820304  
 PDR ADDCK 03000320  
 PDR

is a part of the General Public Utilities System

*Handwritten initials*



LICENSEE EVENT REPORT

NARRATIVE REPORT

TMI-II

LER 82-07/03L-0

EVENT DATES - January 20, and 26, 1982

I. EXPLANATION OF OCCURRENCE

On two occasions the Auxiliary Building Ventilation System was declared inoperable due to low exhaust flowrate. Each occurrence placed the unit in the action statement of Technical Specification 3.9.12. On the first occasion the Auxiliary Building Ventilation System was declared inoperable at 1050 hours on January 20, 1982. The system was returned to operable status when the flowrate was restored at 1210 hours on the same date.

On the second occasion, the ventilation system was declared inoperable at 0915 hours on January 26, 1982 and returned to operable status when the flowrate was restored at 0920 hours on the same date.

These events are considered reportable under Section 6.9.1.9(b) due to entry into and compliance with the action statement of Recovery Technical Specification 3.9.12.

II. CAUSE OF THE OCCURRENCE

The cause of each event was traced to a supply fan trip in the Unit 1 Fuel Handling Building at 0945 hours on January 20, 1982 and again at 0910 hours on January 26, 1982. Each fan trip resulted in lowering the pressure in the Unit 2 Fuel Handling Building and Auxiliary Building. Operating as designed, the Unit 2 Auxiliary Building vortex dampers closed partially to maintain the proper  $\Delta P$  between the building and atmospheric pressure. The partial closing of the vortex dampers caused the Auxiliary Building exhaust flowrate to drop below the minimum allowed value for operability.

III. CIRCUMSTANCES SURROUNDING THE OCCURRENCE

At the time of the occurrence, the Unit 2 facility was in a long-term cold shutdown state. The reactor decay heat was being removed via loss to ambient. Throughout the event there was no effect on the Reactor Coolant System or the core.

IV. CORRECTIVE ACTIONS TAKEN OR TO BE TAKEN

IMMEDIATE

No action was taken by Unit 2 personnel, except for communication with the Unit 1 Control Room, since the only means of restoring full exhaust flowrate was to restore the supply air flowrate, i.e., restart the Unit 1 Fuel Handling Building supply fans. The Unit 1 Control Room was notified in each case that the TMI-1 ventilation problem was affecting Unit 2 ventilation, operation.

LONG TERM

Since the occurrence had no initiating cause controlled by Unit 2, the Unit 2 Auxiliary Building Ventilation System did not fail (the vent. system compensated for changing  $\Delta P$  as designed), and there existed no safety related failure or concern (negative pressure within the building was maintained), no further corrective action is considered appropriate.

V. COMPONENT FAILURE DATA

N/A