

**Nuclear**

**GPU Nuclear Corporation**  
Post Office Box 480  
Route 441 South  
Middletown, Pennsylvania 17057  
717 944-7621  
TELEX 84-2386  
Writer's Direct Dial Number:

November 16, 1982  
4410-82-L-0050

Office of Inspection and Enforcement  
Attn: Mr. Ronald C. Haynes, Director  
Region I  
US Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit 2 (TMI-2)  
Operating License No. DPR-73  
Docket No. 50-320  
Licensee Event Report 82-033/01L-0

Attached please find Licensee Event Report 82-033/01L-0 concerning the nonperformance of three surveillances as identified on October 14, 1982.

This event constitutes a violation of Sections 3.7.3.1, 3.7.3.2, and 3.7.3.3 and is considered reportable under Section 6.9.1.8(b) of the Interim Recovery Technical Specifications.

Sincerely,

*B K Kanga*  
B. K. Kanga  
Director, TMI-2

BKK/SDC/jep

Attachments

CC: Mr. L. H. Barrett, Deputy Program Director - TMI Program Office  
Dr. B. J. Snyder, Program Director - TMI Program Office  
Mr. V. Stello, Deputy Executive Director

8211290220 821116  
PDR ADDCK 05000320  
S PDR

*TEU*

**LICENSEE EVENT REPORT**

Attachment 1  
4410-82-L-0050

CONTROL BLOCK: 

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59

P A T M I 2 0 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

## CON'T

01 REPORT SOURCE L 6 0 5 0 0 0 3 2 0 7 1 1 4 8 2 8 1 1 1 5 8 2 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On October 14, 1982, a condition determined ~~reportable~~ was realized. On July 14,

03 | 1982, the RCS was depressurized to allow performance of the Quick Look project. The

04 | scope of the project was expanded such that the original two week schedule has been

05 | exceeded. The extended schedule resulted in delaying performance of surveillances |

**06** | beyond the schedule flexibility allowed in Section 4.0.2 of the Recovery Operations |

07 | Plan. This event had no effect on the health and safety of the public.

08 \_\_\_\_\_

7 8 9 10 11 12 13 14 15 16 17 18 19 20

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 C J A X Z Z Z Z Z Z Z Z Z Z Z Z Z Z

(17) LER RD REPORT NUMBER	EVENT YEAR [ 8   1   2 ] 21 22	REPORT NO. [ 0   3   3 ] 23 24 26	CHECKED [ / ] 27	COOR [ 0   1 ] 28 29	REP. TYPE [ L ] 30	REASON [ 0 ] 31 32		
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS [ 0   0   0   0 ] 37 38 39 40	ATTACHMENT SUBMITTED	FORM-D-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
[ 3 ] (18)	[ Z ] (19)	[ Z ] (20)	[ Z ] (21)	[ 0   0   0   0 ] (22)	[ Y ] (23)	[ N ] (24)	[ Z ] (25)	[ Z   9   9   9 ] (26)
33	34	35	36	37	41	42	43	44

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause has been identified as the failure to anticipate the need for a Recovery |

**11** | Operations Plan Change Request (ROPCR) as a result of the extended schedule impacting

172 | surveillance performance. ROPCR #21 was submitted on November 11, 1982. Selected |

13 | departments are reviewing this event in order to ensure cognizance and avoid similar |

14 | occurrences.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS      % POWER      OTHER STATUS      METHOD OF DISCOVERY      DISCOVERY DESCRIPTION

1 5 [X] 28 0 0 0 29 Recovery mode 30 D 31 Inquiry by NRC 32

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 2 33 2 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)  
N/A

LOCATION OF RELEASE (36)  
N/A

45 46

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7		0	0	0	37	2	38	N/A

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	H	0	0	40	N/A

19		Z		43		DESCRIPTION		43	
						N/A			

7 8 9 10 80  
PUBLICITY  
ISSUED DESCRIPTION (45) 8211290226 821116  
PDR ADQCK 03000320 NRC USE ONLY  
S PDR

NAME OF PREPARER Steven D. Chaplin

PHONE: (717) 948-8461

LICENSEE EVENT REPORT  
NARRATIVE REPORT  
TMI-II  
LER 82-033/01L-0  
EVENT DATE - October 14, 1982

I. EXPLANATION OF OCCURRENCE

The event was the failure to perform required surveillances for three Technical Specification required systems. The surveillance procedures (systems) involved are:

- 4303-M25                      Decay Heat Closed Cooling Water pump operability and valve operability test
- 4303-M30A/B                Nuclear Services Closed Cooling Water pump operability test and valve operability test
- 4303-Q3                      Mini Decay Heat Removal pump functional test

These surveillances were initially delayed to allow continuance of the Quick Look project. The delay was necessary and intentional to ensure control over potential boron dilution accidents as discussed in Appendix C of the Quick Look Safety Evaluation submitted on July 6, 1982, via GPU letter 4400-82-L-0110, and approved by the NRC (Dr. B. J. Snyder to J. J. Barton dated July 13, 1982).

Following NRC approval of the Quick Look Safety Evaluation and implementing procedures, GPU de ressurized the RCS on July 14, 1982. Had the RCS been re ressurized after the originally projected two week schedule, it would not have adversely impacted surveillance performance (i.e. delay the surveillance testing beyond the allowed surveillance schedule flexibility provided in Recovery Operations Plan 4.0.2).

The surveillances have not been performed since commencement of the Quick Look project because the procedures implementing the Quick Look Project required that surveillances on certain systems be suspended for the duration of the project in accordance with the Quick Look Safety Evaluation.

This constitutes a violation of Technical Specification 3.7.3.1, 3.7.3.2, and 3.7.3.3 and is considered reportable pursuant to Section 6.9.1.8(b) of the Recovery Technical Specification.

II. CAUSE OF THE OCCURRENCE

The cause of the event has been identified as the failure, on the part of GPU, to anticipate the need for, and to submit in an expeditious fashion, a request for a change to the Unit 2 Recovery Operations Plan once the schedule for the Quick Look was extended such that it could adversely impact performance of required surveillance testing.

III. CIRCUMSTANCES SURROUNDING THE OCCURRENCE

At the time of the occurrence, the Unit 2 facility was in a long-term cold shutdown state. The reactor decay heat was being removed via loss to ambient. Throughout the event there was no effect on the Reactor Coolant System or the core.



IV. CORRECTIVE ACTIONS TAKEN OR TO BE TAKEN

Recovery Operations Plan Change Request No. 21 was submitted on November 11, 1982, via GPU letter 4410-82-L-0043. It would allow suspension of surveillance testing via NRC approved procedures pursuant to Technical Specifications 6.8.2 without requiring a change to the Recovery Operations Plan.

In addition, this event is being utilized as an example to various departments in GPU to indicate the need to ensure change requests to upper tier Licensing documents are initiated as necessary. This review will be completed by November 30, 1982.

V. COMPONENT FAILURE DATA

N/A