B&W 03 1983



GPU Nuclear Corporation

Post Office Box 480 Route 441 South Middletown, Pennsylvania 17057 717 944-7621 TELEX 84-2386 Writer's Direct Dial Number:

April 28, 1983 4410-83-L-0089

Office of Inspection and Enforcement Attn: Mr. J. M. Allen Acting Regional Administrator Region I US Nuclear Regulatory Commission 631 Park Avenue 19406 King of Prussia, PA

Dear Sir:

Three Mile Island Nuclear Station, Unit 2 (TMI-2) Operating License No. DPR-73 Docket No. 50-320 Licensee Event Report 83-012/03L-0

Attached please find Licensee Event Report 83-012/03L-0 concerning the inoperability of the Air Intake Tunnel Halon System on March 29, 1983.

This event concerns Section 3.7.10.3 and is considered reportable under Section 6.9.1.9(b) of the Interim Recovery Technical Specifications.

B. K. Kanga

Director, TMI-2

BKK/RDW/jep

Attachments

CC: Mr. L. H. Barrett, Deputy Program Director - TMI Program Office Dr. B. J. Snyder, Program Director - TMI Program Office

8305110321 830428 PDR ADOCK OSOOOSO

NRC FORM 366 (7-77) Air intake tunnel halon outland declared U.S. NUCLEAR REGULATORY COMMISSION Attachment 1 4410-83-L-0089
CONTROL BLOCK: 1 1 1 2 9 8 5 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
1 8 9 LICENSEE CODE 14 15 15 LICENSE NUMBER 25 3 4 1 1 1 1 1 1 3 5 5 CAT 58
CON'T O 1 SOURCE L 6 0 5 0 0 0 0 3 2 0 7 0 3 2 9 8 3 8 0 4 2 8 8 3 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 Following an inadvertent discharge of one of the zones of the Air Intake Tunnel (AIT)
Halon System, the six Halon bottles in the zone were recharged. The pressure of one
old of the bottles, EI-4C, was below the chart in Surveillance Procedure 4331-SA1. A cal-
ols culation of the pressure limit determined that the pressure of EI-4C was below the
olf limit defined in Tech Spec 3.7.10.3. The AIT Halon System was declared inoperable at
0 7 Lilli hours on March 29, 1983. This event had no effect on the health and safety of
the public.
SYSTEM CODE SUBCODE SU
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) This event was caused by two personnel errors: 1) Plant engineering failed to per-
form the calculation for the pressure limit of EI-4C in a timely manner; and, 2) Plant
maintenance prematurely returned the Halon System to service based on an assumption that the pressure of EI-4C was acceptable. The bottle was repressurized and personnel
were counseled. The Surveillance Procedure is being revised. By FACILITY METHOD OF
STATUS SPOWER OTHER STATUS OF DISCOVERY DISCOVERY DESCRIPTION (32) 1 5 X 28 0 0 0 0 29 Recovery Mode A 31 Engineer determination
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 N/A 7 8 9 10 11 PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 N/A 44 45
1 7 8 9 PERSONNEL IN HERES 13 80
NUMBER DESCRIPTION (41) N/A 1 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION N/A 9305110326 830428 PDR ADDCK 05000320
1 9 Z 42 PDR N/A S PDR
PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY N/A
7 8 9 10 68 69 80.5 NAME OF PREPARER RUSS Wells PHONE (717) 948-8461

LER 83-012/03L-0 EVENT DATE - March 29, 1983

I. EXPLANATION OF OCCURRENCE

At 1111 hours on March 29, 1983, the Air Intake Tunnel (AIT) Halon System was declared inoperable as a result of the following event:

On March 3, 1983, there was an inadvertent actuation of one of the four zones of the AIT Halon System (see LER 83-09). The halon bottles in this zone were returned to the vendor for recharging, and were reinstalled on March 18, 1983. Maintenance crews recorded the bottle pressure for each bottle as it was installed. The pressure of one of the six bottles, EI-4C, was below the chart provided in Surveillance Procedure 4331-SAI; therefore, by procedure, the plant maintenance contacted plant engineering and requested a calculation of the pressure limit for the bottle EI-4C. Prior to the completion of the calculation, the AIT Halon System was prematurely returned to service. When the calculation was performed on March 29, 1983, it was determined that the bottle pressure for EI-4C was below the limit defined in Technical Specification 3.7.10.3. The AIT Halon System was then declared inoperable.

On March 30, 1983, the Maintenance crew repressurized bottle EI-4C to an acceptable level. The AIT Halon System was then returned to operable status, thus complying with the Action Statement of Technical Specification 3.7.10.3.

This event is considered reportable pursuant to Technical Specification 6.9.1.9(b) due to entry into and compliance with the Action Statement of Technical Specification 3.7.10.3.

II. CAUSE OF THE OCCURRENCE

The cause of this event was due to a breakdown in communications. As mentioned previously, on March 18, 1983, plant maintenance requested from plant engineering a calculation for the pressure limit for the bottle EI-4C. The calculation wasn't performed until March 29, 1983. Since maintenance was not informed of the results of the calculation, the AIT Halon System was prematurely returned to service on March 18, 1983, based on an assumption that the bottle pressure for EI-4C was acceptable.

III. CIRCUMSTANCES SURROUNDING THE OCCURRENCE

At the time of the occurrence, the Unit 2 facility was in a long-term cold shutdown state. The reactor decay heat was being removed via loss to ambient. Throughout the event there was no effect on the Reactor Coolant System or the core.

IV. CORRECTIVE ACTIONS TAKEN OR TO BE TAKEN

Short Term

The maintenance crew repressurized bottle EI-4C to an acceptable level.

Long Term

Appropriate plant maintenance and plant engineering personnel were counseled regarding the circumstance and cause of this event; and specifically regarding 1) the importance of completing calculations for pressure limits in a timely manner, and 2) verifying the results of the pressure limit calculations before returning the AIT Halon System to service. Additionally, before the next planned maintenance on the halon bottles scheduled for September 1983, the acceptance criteria temperature/pressure scale of 4331-SAI will be extended to 100° F.

V. COMPONENT FAILURE DATA

N/A