

TASK CLOSE OUT DOCUMENT

Task Scope Instrument Development
Consolidation of Shift Summary
Reports

To: M. Levenson
S. Levy
E. Zebroski

Task No. 11-4

Date Complete 2/14/70

Reason, felt task is complete:

Reported

Members of Committee

J.C. Pollock
Ch. Ziegler

[Signature]
Signed
Committee Leader

POOR ORIGINAL

TO: SIG DISTRIBUTION

April 14, 1979

Attached is a complete compilation of the shift result summaries of the reactor diagnostics by noise analysis covering the period April 8, 1979 through April 12, 1979.

These activities have been reduced in scope to just a routine continuous monitoring with a fast-respond capability if any unexpected system changes occur. No further shift report will be prepared, but if any system changes occur a special summary report will be issued.



Norbert J. Ackermann, Jr.
SIG Coordinator

NA:ms

Vie Stille, NRC

4/5/79

T. J. Abernathy Jr.

Noise Analysis Monitoring of TMI-2

Objectives:

1. To assist in monitoring the status of the reactor system, particularly during transient conditions to give supplementary and complementary information relative to that in control room.
2. To monitor the integrity of various process and special signal channels by signature analysis and trending analysis to give early warning of instrumentation failure and failure mode;
3. To provide secondary monitoring capability in case of failure of primary capability.

Procedure:

1. Provide continuous strip chart recording of particular signal channels to allow visual correlation among channels and to provide time series trending capability;

(2)

2. Perform spectral analysis on selected signal channels periodically to perform signature analysis and trend analysis

Signal Channels Monitored:

From Patch Panel

Patch Panel #

- | | |
|--------------------------------------|----|
| 1. RC Pressure Loop A | 24 |
| 2. RC Pressure Loop B | 25 |
| 3. Pressurizer Level (uncompensated) | 23 |
| 4. Pressurizer Level (compensated) | 22 |
| 5. Temperature Loop A | 31 |
| 6. Make-Up Tank Level | 96 |
| 7. Main Steam Pressure A | 58 |
| 8. Main Steam Pressure B | 59 |
| 9. OTSG Level A | 49 |
| 10. OTSG Level B | 51 |
| 11. Flow Loop A | |

From Signal Cabinets

1. Loss Parts Monitor Channels 1-10
2. Incore Thermocouple Channels
3. Incore Flow Detectors
4. Pressurizer Temperature

Noise Analysis Station

~~4/1/79~~
4/1/79
G.L. Zelen

6:30 AM,

05/04/79

1. Loose Parts Monitoring:

- a. No indication of metallic impacts
- b. Sensor # 3, Upper Reactor Vessel A, is showing symptoms of advanced degradation.
- c. Sensor # 4, Upper Reactor Vessel B, appears to occasionally exhibit symptoms of degradation.

2. Sensor Performance Degradation:

The following ~~sensor~~ plant parameters are being trended by ~~the~~ Spectral Analysis every two hours:

	Patch #
OTSG B Pressure, Steam	113
OTSG A Pressure, Steam	112
RCS Pressure A Loop, Wide Range	29
RCS Pressure B Loop, Wide Range	25
OTSG "A" Level Operating Range	49
OTSG "B" Level Operating Range	51
For OTSG A Downcomer Temp	53

Every 1/2 hour, Pressurizer Level 2
2004 202
spectra is obtained for comparison with

3. RCS Pressure Fluctuations.

a. RCS Wide Range Pressure A exhibits occasional [7 events] between 2130 hrs and 0630 hrs) small step changes indicative of potential sensor degradation. The number of these step changes has increased in the last 10 hours. These step changes are uncorrelated with other plant parameters.

b. The pressure noise amplitude continues at the same typical peak-to-peak values as during the previous 48 hours.

4. In-Core Thermocouple Measurements

Reference attached ORNL report.

5. Administration:

a. Procured "In-core Instrumentation, Self Powered Neutron Detector Noise Analysis Procedure 2-44 Rev 3."

b. Introduced for coordination by GPU/HFE
"Ex-core Detector Noise Analysis & Measurements" procedure.

6. Plans:

2004 204

a. Core Parts Monitoring, Sensor Performance Degradation and RCS Pressure Fluctuations monitoring

- b. ORNL to perform noise analysis
on in-core self-powered neutron
detectors per procedure ~~Z-44~~^{Z-44} rev 1
- c. Ex-core ion chamber noise
analysis to be performed ~~beginning~~ starting
~~at~~ 2100 hrs, 05/09/79.

4/4/79

W. J. Anderson

Summary of Findings for 4/4/79

1. A loop & B loop pressure excursions at ~1815hrs on 4/3 were correlated in time at initiation with each other & with LPM channels 1, 4, 7 & 7 per B & W strip chart recording. No correlation in other channels with termination of the 2 pressure excursions ??
2. TMI Operation has begun cycling pressure & pressure level again giving appreciable slow transients.
3. Investigators are looking at inert self powered detectors & find a few still working & suggest they be more investigated.
4. Above hooked up the pressure Temp. (dual element RTD at 305 simulation with no flushing at RC2-TT2 side). The strip chart reading of 590°F corresponds to some computer reading not calibrated properly as shown.
5. Pressure, Matt, Roger & Paul had in pressure RTD input could be used as single point but indicate in pressure

POOR ORIGINAL

2004 206

4/4/79
r. J.A. Findling

by cycling level so sensor sees liquid then
fluid, etc. Self heating test would show
dramatic resistance change from change
in cycling medium. Need very
good constant current source (20-30ma)
and access directly to RTD bridge. In setting
up call Robbie for info support (home # 615-693-520).

6. TC noise should focus on increased
boiling detection and on pre-TC
cross-correlation.

No change in level #2 & level #3
signals today (lots of switching noise as
don't get caught with it).

8. LPM quiet all day.

POOR ORIGINAL

9. JCP wants to know:

1. current thru RTD for give 2-reading
2. Indicated Temp reading
used for determining S/N in self-heating test.

* Call Newman & Bull at 301-492-2001
at 2000 hrs!

2004 207

10. Watch pressure Temp if we get any more
long steps in A or B long pressure.

4/4/79

W.A. Finsler

12. Continue taking Level 2 PSD's every 30 min and Level 3 PSD's every 1 hour.
13. Plan out a long-term surveillance & diagnostic support to monitor long-term cool down with eventual goal to attempt to restore natural circulation with maximum oversight in case of further trouble.

cc: Fry
Kryter
Mays
Zigler

POOR ORIGINAL

04/07/79

G.L. Ziegler

0630 hrs Noise Analysis SummaryRCP 1A Evaluation:

No significant events were detected by the Loose Parts Monitor during the R.C.P 1A trip and start-up of RCP 2A. The RCS pressure fluctuations for A Loop increased by a factor of approximately 2 whereas the Loop B fluctuations increased by a factor of 1.7. ~~The~~ In-core thermocouple noise measurements in progress exhibited no significantly obvious changes.

RCS Pressure Evaluation:

2004 209

At approximately 23:25 hrs of 04/06/79 the RCS pressure reached a low of approximately 850 psia. The Pressure oscillations for Loop A decreased to a minimum of a factor

of 2 lower before returning to its original values after the RCS pressure increased just 900 psia. The pressure fluctuations decreased by a factor of 5 on the RCS Loop B signal prior to returning to its original value.

Incore Detectors:

Resistance and capacitance measurements using spectral analysis techniques were obtained for three incore neutron detector strings. These measurements will be used by incore analysts to evaluate the incore readings obtained by standard techniques in light of the uncertainty introduced by the "battery" effect.

Sewer Degradation Monitoring

No significant changes were observed during the last 24 hours.

4/8/79

POOR ORIGINAL

Shift: 7:00 AM to 7:00 PM

By: J.C. Robinson

Subject: Significant observations & occurrences.

When taking over from Ziglar, the operators were attempting to vent out pressure at 550 psia. At 550 psia, the behavior of pressure noise signals were:

A loop: At first reaching lower pressure, the noise reduced from ~50 psia to ~25 psia.

B loop: The noise decreased from ~15 psia to < 5 psia.

As the pres was vented, the ^{pressure} noise signals began to increase back to their original values prior to reducing pressure. The behavior of the B loop pressure always lead the A loop.

2004 212

When this process was repeated at 500 psi, the A loop noise signal returned to ~40 psi (instead of 50 as had been observed on all previous pressure

levels) and the B loop increased to ~20 psi noise (becoming more symmetric than in times past).

After degaussing was complete at 500 psi, the operators went into a "spraying" (ie pressurizer) mode of operation for 2 hr. at const pressure. This was followed by opening vent valves for ≈ 30 min. During this mode, the noise level on the A loop pressure signal slowly decreased (over ≈ 40 min) to the level it reached on ~~loop~~ reducing pressure. The B loop pressure did not change during this time (remained about 20 psi p-p). When the valves were ^{2004 213} vented, the A loop pres. noise slowly returned to its' ~40 psi p-p amplitude at 500 psi. When the pressure signals were increased, the noise level of the A loop returned to its' ~50 psi p-p and the B loop went

POOR ORIGINAL

back to its' ~ 12 psi pp skewed negative fluctuation

The temperature profiles (in core \pm) looked reasonably stable throughout the day. I could see no significant change in the results at 500 psi and 750 psi.

B&W personnel ran spectra on the A & B loop pressure signals. Did not see the pump turning speed (~ 19.4 Hz), but did see strong resonances in the 6.4 - 6.8 Hz range in A & B loops (plus their harmonics).

POOR ORIGINAL

10/11/11

G.L. Ziegler

Noise Monitoring Summary

Time: 0615 hrs Period: 1900 hrs - 0700 hrs Date: 8/9 April

Loose Parts Monitoring:

No unusual noises indicative of metal-to-metal impact were detected. ~~Noises~~ Noises encountered were anticipated for the condition of the plant.

Sensor Performance Monitoring:

No significant deviations from baseline signatures were detected for the plant parameters and/or sensors monitored.

RCS Pressure Fluctuations:

2004 215

In accordance with SOP Z57, Part 1, the RCS primary system pressure was reduced from 700 psig to 400 psig. RCS pressure fluctuation for A loop allowed expected behaviour for pressure reductions and venting. On return to 500 psig, A loop peak-to-peak amplitudes was estimated to be approximately

the same as on the way down, i.e., ≈ 40 psig peak-to-peak. B Loop pressure fluctuations exhibited an increase to ≈ 18 psig peak-to-peak amplitude, vs. from a typical 7 psig peak-to-peak prior to this last evolution. The increase in the B loop pressure fluctuations is further evidence of "hardening" of the system from a dissolved gas point of view.

Other Measurements:

Ex-Core Ion Chambers: Spectral analysis on 5 pairs of detectors were performed. No cross-correlation was observed. No significant information was identified in the AC component of these signals.

2004 216

H-8 Core Location Monitoring: Noise measurements were performed at 450 psig and at 400 psig on the in-core thermocouple at core location H-8. No significant deviations were observed from

Baseline measurements taken at 600 p.m. were observed. It should be noted that thermocouple H-8 exhibited less "noise" than ~~the other~~ than other thermocouples exhibiting a lower D.C. (i.e., temperature) value.

In-Core Neutron Detectors: Spectral analysis was performed on the three SPNDs at core location 13-C which ~~are~~ are considered still operable. They are located on levels 1, 3, and 5. No significant information was identified in the A.C. component of these signals.

JC Robinson

Noise Monitoring Summary

Time 18:40

Period: 0700 → 19:00

4/9/79

Loose Parts Monitoring

Only low level "banging" is being heard which has been heard from the start as monitored by B & W personnel.

RCS Pressure Fluctuations

The system pressure has been held between 900 and 1000 psi throughout the duration of this shift. The noise on the A pressure signal has remained stationary at ~50 psi p-p and that on the B pressure signal has remained steady at about 7 psi p-p. Extensive spectral analysis (attached) has been carried out on these signals. We concluded (at least for frequencies > 1 Hz) that 2004 218 A loop is driving the B loop. The dominant frequency of the loops are different. We should

continue monitoring the resonant frequency to see if they tend to come together as the gas is removed.

The temperature profiles ^{from} the incense ~~detectors~~ thermocouples are remaining stable and continuing to decrease.

Analysis of A & B pressure signals.

For A pressure signal (see Fig 1), we observed a sharp resonance at 6.65 Hz and its harmonics. The B pressure signal (see Fig 2) has the same 6.65 Hz (+harmonics) and other structure. In particular, a resonance (+harmonics) is present at 8.046 Hz (see Fig 3). We postulated A loop is driving B loop (A loop resonance frequency is 6.65 Hz , B loop resonance frequency is 8.046 Hz). If so, we should see the sum and difference in their frequencies. The sum (14.7) is shown in Fig 4. The difference (11.41) is shown in Fig 5. This data supports the postulate:


1. A loop has a resonance freq. of 6.65 Hz at these conditions.
2. B loop has a resonance freq. of 8.05 Hz at these conditions.
3. A loop is driving (force modulating) B loop.

From data B & W run earlier at lower pressure, we know that the A loop resonance decreased slightly. If B loop ^{resonance} were to decrease at a faster rate, then the noise in the B loop (if the resonance were not used) would increase. We will observe this as the pressure is decreased.

QCP & ONF


* Since the B loop is driven by the A loop, as the resonance of the two loops come together (in a certain way), there will be a more constructive transfer of energy.

RUN 2
TMI A-LOOP PRESS.
16:45 4/9/79
PRESSURE = 950psi
SETUP NO. 2



RUN 2 A-Loop signal PSD
Fig. 1

RUN 2
TMI B-LOOP PRESS.
16:45 1/9/79
PRESSURE = 950psi
SETUP NO. 2



RUN 2 B Press signal PSD

Fig. 2

X₀ 8. 8463
A SPEC 2
10. 000

Y₀ -17. 985

#A₀ 180

HARMONIC


RUN 2

TMI B-LOOP PRESS.

16:45 4/9/79

PRESSURE = 950 PSI

SETUP NO. 2




RUN 2

Fig. 3


C

RUN 2
TMI B-LOOP PRESS.
16:45 4/9/79
PRESSURE = 950 psia
SETUP NO. 2



RUN 2
Fig. 4

RUN 2
TMI-B-LOOP PRESS.
16:45 1/9/79
PRESSURE = 950PSI
SETUP NO. 2



RUN 2
Fig 5

2004 225

Noise Monitoring Summary

G.L. Zigler

Date: 9/10 April 79

Time: 0630 hrs

Period: 1900hr - 0700hr

Loose Parts Monitoring:

No unusual noises indicative of metal-to-metal impact were detected.

Sensor Performance Monitoring:

At 1735 hrs LT-2 ^(Pressure-zero Level) exhibited erratic behaviour by spiking to full scale value and returning back to correct indication. No switching or electrical checks were being performed. LT-3 was switched as the main ~~the~~ level indicator at ~~the~~ the onset of the erratic behaviour of LT-2. ^{3004 226} Two

minutes later, LT-2 was switched back on and indicated normal behaviour. Spectral analysis before and after this occurrence indicated no significant changes.

At 0455 hrs the computer trending of LT-2 indicated another transient peaking. The computer values of such fast transients should be taken with caution in view of the one minute sample period.

No readings can be made of the two non-controlling ^{pressurizer} level indicators by noise analysis personnel in order to assess their status.

2004 227

Remaining plant parameters and

runners being tracked showed no indications of degradation.

RCS Pressure Fluctuations:

RCS pressure remained between 1000 and 800 psig. RCS pressure fluctuations exhibited no significant changes during this reporting period.

Other Activities:

This uneventful period was spent in further documentation and investigation of the spectral characteristics of the RCS pressure fluctuations. These

investigation concentrated on the ①
lower portion of the spectrum (below 2 Hz
which contain about 90% of
the ~~unwanted~~ signal content of the A-loop
fluctuations. Other activities included
documentation and general cleaning-up
of previous operations.

JC Robinson
Noise Monitoring Summary

Time 17:28 Period 0700 → 17:00

4/10/79

Load Parts Monitoring

The tingling sound that has been heard is not being heard now.

SPD:

Some of the SPD's were being striped out. These readings increased about 08:30. This was found to be introduced - by an analysis being used. Very essential. Check off In-line Thermocouples but this time revealed no change between 07:00 and 09:00.

Pressure Level Indicators.

Both LT-2 and LT-3 indicators gave some erratic behavior throughout the day. The LT-2 indicator has been very stable. Throughout the pressure decrease which began at 13:37. The behavior in sharp spikes on strip chart which could conceivably be introduced by power supply. This possibility is being explored!

2004 230

Pressure Decent.

The pressure had been reduced to 450 psi at 17:00. This operation went very smoothly. There was no apparent gas (requisite) reduction in pressure noted down to this pressure (was reduced to 450 psi previously). At about 450, the noise on pressure

signal began to increase and that in the A loop began to decrease (as observed previously). The spectra revealed that the $\sim 6.7 \text{ Hz}$ peak in A has decreased slightly. The $\sim 8.0 \text{ Hz}$ in B has decreased significantly to $\sim 6.9 \text{ Hz}$. It appears that the noise in both loops are tending toward the same order of magnitude and similar high frequency behavior.

Thermocouples (In-core)

The in-core thermal couples 7F and 8F are continuing to read low (less than the inlet water). We looked at the noise on these couples and decided they appear as valid as any other couples. Further, these sensors are trending downward with all other readings with time. Thus, we postulate these couples are shorted out ~~which would~~ (to the steel) which would be a thermal couple with a smaller emf/degree and hence "small" readings.

Noise Analysis Summary

G. L. Ziegler

Time: 1600 - 1900 hrs

4/10/79

RCS Pressure Evolution:

SOP Z-57 Rev 2 was used to bring ~~the~~ RCS pressure to 500 psig and vent at 450 psig. Pressure was dropped to 425 psig for baseline measurements of the back-up pressurizer level ~~instrumentation~~ instrumentation. Pressurizer level increased to 250 inches and let-down could not keep up with the level increase. Z-57 Rev 2 was started by increasing pressure to 550 ~~psig~~ psig and venting while holding 550, and increasing to 800 - 900 psig. RCS pressure fluctuations behaved as expected with good outgassing occurring at the 550 vent.

2004 232

Incore Instrumentation Checks

TDR techniques were attempted

(2)

on the in-core instrumentation. In agreement with previous experience in the use of this technique with oxide cables the results were inconclusive. No significant new information was obtained on the structural integrity of these detectors.

2004 233