

TEAM CLOSE OUT DOCUMENT

Task Scope \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

To: M. Levenson  
S. [unclear]  
E. [unclear]

Task No. \_\_\_\_\_ Date Complete 11/1/01

Reason felt task is complete:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Members of Committee

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

*[Signature]*  
\_\_\_\_\_  
Signed  
Committee Leader

POOR ORIGINAL

160 144

7905220063

April 18, 1979

TO: SPECIAL INSTRUMENTATION  
GROUP DISTRIBUTION

The attached is a summary report of the instrumentation diagnostics performed by Combustion Engineering personnel under Lionel Banas.

*Norbert J. Adlermann, Jr.*

Norbert J. Adlermann, Jr.  
SIG Coordinator

NA:dr  
Attachment

160 145

# INSTRUMENTATION

WORK SUMMARY

4/2 to 4/13/76

3 Mile Island - Unit 2

L. BRADY

COMPUTER ENG.

1. Following Test Program was Accomplished:

Z-44 - Incore Instrument Analysis

Z-66 - Incore Computer Input Measurements

Z - Backup Program on T/C  
in Control Room.

## Incore Instrument Program:

Five SPND's were checked for operation.

The following SPND's were found

FUNCTIONAL SEE TEST INSTRUMENT FOR DATA

8H - 1, 2, 3      8B-1      6C-1, 2

9H - 1      7N-2      10R-1, 4

6L - 1, 2      6C-1, 2      11D-1

8N - 2, 3      5D-2      12D-1, 2, 3

9N - 1      4E-1, 2      13L-1, 2

11L - 1      3F-1, 2      13C-1, 3, 5

12K - 1, 2      2G-1, 2

13H - 1, 2      3L-1, 2

13G - 2      3M-2

11E - 1      4N-1, 2

10C - 1, 2

160 146

Subsequent to the test procedure,  
Several of the "good" sensors subsequently  
Failed. It is felt that most of the good  
remaining SPND will fail during  
long term shutdown.

Temperature sensitivity of the failed SPND  
due to moisture in the cells has not  
been established. Data analysis of  
SPND's logged on "Lora" during  
plant cooldown may show this  
relationship. It is recommended that  
SPND signals be treated with RCS  
temperature during cooldown evaluation.

The Movable Detector was encrusted -  
driven 3' into the actin core region.  
The detector is failed giving a high  
current reading. Long term irradiation  
showed a response but the dose is  
what is unknown. The Movable Detector  
was subsequently withdrawn. Attempts  
to reinsert was unsuccessful. The  
detector is presently 3 ft below the  
actin fuel. A trend was started on  
cooldown. The chart recording is  
still in the machine.

Computer modifications were performed on selected SPND inputs to gain the current such that the computer could read the small (1-2 nA) currents. Test procedure Z-65 installed 1 MEG resistors in specific locations. Note that computer print out on these detectors are not true but rather must be reduced by a factor 1/200 to true nA range readings. This is the gain ratio  $1 \rightarrow 1/200$  5K/1MEG.

Time Domain Reflectometry was performed on several T/C & SPND's in order to attempt to resolve the location of failure. These attempts were unsuccessful. Benchmark cable lengths were uncertain and pulse return was too feeble to be accurate. Tests of a Unit 1 SPND was attempted to provide a reference. See Island Drigle's report for results.