March 27, 1985

Docket No. 50-320

Mr. F. R. Standerfer Vice President/Director Three Mile Island Unit 2 GPU Nuclear Corporation P.O. Box 480 Middletown, PA 17057

Dear Hr. Standerfer:

Distribution: Docket No. 50-320 NRC PDR Local PDR TMI HO R/F TMI Site R/F DCS BJSnyder **WDTravers** TCPoindexter MMasnik RAWeller. PGrant RCook CCowgill LChandler, ELD IE (3) LSchneider TBarnhart (4) ACRS (16) OPA SECY

Subject: Three Hile Island Nuclear Station Unit 2 Operating License DPR-73 Docket No. 50-320 Polar Crane Auxiliary Hoist Operational and Load Test M-town Office

On November 14, 1984, General Public Utilities Nuclear Corporation (GPUNC) requested NRC approval of the Polar Crane Auxiliary Hoist Inspection and Refurbishment Plan. On January 18, 1985 GPUNC also submitted the Auxiliary Hoist Load Test Safety Evaluation Report for NRC review and approval. We have reviewed both documents and have propared the enclosed safety evaluation. The NRC staff's review focused on the following areas: refurbishment methodology, including the replacement of unlike kind parts, the replacement of the wire rope, the refurbishment of the brakes, general auxiliary hoist component inspections, quality assurance involvement during the refurbishment and load test, load test components and worker exposure.

Based on our detailed review as discussed in the enclosed Safety Evaluation, we conclude that:

- Pending the successful completion of the proposed Auxiliary Hoist (AH) operational test, the AH will be functionally ready for the load test.
- According to information provided by the licensee, all unlike kind replacements were either recommended by the vendor, or functionally equivalent or functionally superior to the original component.
- The replacement of the wire rope was satisfactorily completed with a like-kind component.
- The inspection and maintenance plans for the AH are adequate to ensure its safe use.
- 5. The planned load test sequence, not withstanding exceptions taken to certain ANSI standards, is sufficient to demonstrate the ability of the ANI to lift 25 tons and be used throughout the THI-2 cleanup.

	(10-80) NRCM 0240	······	OFFICIAL	RECO	RDC	OPY]	1.7517	USGPO: 1981-335-960
SURNAME	TCPOINTExter 3/JV85	bg BAleller 3/1 85	BJSnyder' 3/27/85		B504 PDR	OBOO97 ADOCK	8503	27 0320	
OFFICE	THE OATRR	SCHENRO NRE	PD TMIPO NR	R					

IIr. F. R. Standerfer

and a

- Quality assurance, quality control and procedural controls for the auxiliary hoist's refurbishment and requalification are sufficient to ensure the safe use of the hoist/crane and the safety of the planned test.
- 7. The likelihood of a load drop is extremely small and even if a drop did occur, the consequences of such an event are bounded by the staff's Safety Evaluation for the Refurbishment of the Reactor Building Polar Crane, Load Test and Recertification for Use, dated November 18, 1983.
- 8. The estimated occupational exposure for the load test is significantly less than that predicted by the staff's Supplement to the Programmatic Environmental Impact Statement dated October 1984.
- Based on the criteria contained in 10 CFR 50.59, the AH operational and load tests do not constitute an Unreviewed Safety Question.

Therefore, the Polar Crane Auxiliary Hoist Inspection and Refurbishment Plan and the load test safety evaluation are acceptable as stated in our enclosed Safety Evaluation.

Sincerely,

Original signed by Michael T. Masnik for

Bernard J. Snyder, Program Director Three Mile Island Program Office Office of Nuclear Reactor Regulation

Enclosure: As stated

cc: T. F. Demmitt

- R. E. Rogan
- S. Levin
- R. L. Freemerman
- J. J. Byrne
- A. H. Miller
- Service Distribution List
 - (see attached)

	(10-80) NRCM 0240		OFFICIAL	RECORD C	OPY	USGPO: 1961-335-980
DATE						
SURNAME						
OFFICE						
Setting and	and the second stand	olaline, gaz si Ber	and the Court of	and the second second		and the second second

TMI-2 SERVICE LIST

Dr. Thomas Murley Regional Administrator, Region 1 U.S. Nuclear Regulatory Commission 631 Part Avenue King of Prussia, PA 19406

.

John F. Wolfe, Esq., Chairman, Administrative Judge 3409 Shepherd St. Chevy Chase, ND. 20015

Dr. Oscar H. Paris Administrative Judge Atomic Safety and Licensing Board Panel U.S. Nuclear Regulatory Commission Mashinaton, D.C. 20055

Dr. Frederick H. Shon Administrative Judge Atomic Safety and Licensing Board Panel U.S. Nuclear Regulatory Commission Mashington, D.C. 20555

Karin W. Carter Assistant Attorney General 505 Executive House P.O. Box 2357 Marrisburg, PA 17120

Dr. Judith H. Johnsrud Environmental Coalition on Muclear Power 433 Orlando Ave. State College, PA 16801

George F. Troubridge, Esq. Shaw, Pittman, Potts and Troubridge 1800 M. St., MW. Mashington, D.C. 20036

Atomic Safety and Licensing Board Panel U.S. Nuclear Regulatory Commission Mashington, D.C. 20555

Atomic Safety and Licensing Appeal Panel U.S. Buclear Regulatory Commission Mashington, D.C. 20555

Secretary U.S. Nuclear Regulatory Commission ATTN: Chief, Docketing & Service Branch Mashington, D.C. 20555

Mr. Larry Mochendoner Deuphin County Commissioner P.O. Box 1295 Marrisburg, PA 12106,1285

John E. Minnich, Chairperson, Dauphin County Board of Commissioners Dauphin County Courthouse Front and Market Streets Marrisburg, PA 17101

Dauphin County Office of Emergency Preparedness Court Mouse, Room 7 Front & Market Streets Marrisburg, PA 17101

.

U.S. Environmental Protection Agency Region III Office ATTR: Els Coordinator Curtis Building (Sisth Floor) Sth & Walmut Streets Philodelphia, PA 19105

Thomas M. Gerusky, Director Bureau of Radiation Protection Department of Environmental Resources P.O. Box 2063 Narrisburg, PA 17120

Dan Kennedy Office of Environmental Planning Department of Environmental Resources P.O. Box 2063 Marrisburg, PA 17120 Willis Blaby, Site Manager U.S. Department of Energy P.O. Box 88 Middletown, PA 12052-0111

David J. RcGoff Division of Three Hile Island Programs RL-23 U.S. Department of Emergy Washington, D.C. 20545

William Lockstet 104 Davey Laboratory Pennsylvania State University University Park, PA 16802

Randy Nyers. Editorial The Patriot 812 Narket St. Marrisburg, PA 17105

Robert B. Borsum Babcoti & Wilcos Buclear Power Generation Division Suite 220 7810 Woodmount Ave. Bethesda, MD. 20014

Michael Churchhill, Esq. PILCOP 1315 Malnut St., Suite 1632 Philadelphia, PA 19107

Linda W. Little 5000 Nermitage DR. Raleigh, NC 27612

Marvin I. Lowis 6504 Bradford Terrace Philadelphia, PA 19149

Jane Lee 183 Yalley Rd. Etters,PA 17319

J.B. Liberman, Esquire Berlack, Israels, Liberman 25 droadway New York, NY 10004

Walter W. Cohen, Consumer Advocate Department of Justice Strauberry Square, 14th Floor Marrisburg, PA 17127

Edward O. Swartz Board of Supervisors Londonderry Township RFD #1 Geyers Church Rd. Riddlatown, PA 17057

Robert L. Enupp. Esquire Assistant Solicitor Enupp and Andrews P.O. Box P 407 N. Front St. Nerrisburg. PA 17108

John Levin, Esquire Pennsylvania Public Utilities Comm. P.O. Box 3265 Narrisburg, PA 17120

Monorable Mark Cohen 512 E-E Main Capital Building Marrisburg, PA 17120

Mr. Edwin Kintner Executive Vice President General Public Utilities Muclear Corp. 100 Interpace Parkus Parsippany, NJ 07054

Ad Crable Lancaster New Era B West King Street Lancaster, PA 17602 SAFETY EVALUATION BY THE OFFICE OF NUCLEAR REACTOR REGULATION

GPU NUCLEAR CORPORATION

METROPOLITAN EDISON COMPANY

PENNSYLVANIA ELECTRIC COMPANY

JERSEY CENTRAL POWER & LIGHT COMPANY


DOCKET NO. 50-320

THREE MILE ISLAND NUCLEAR STATION UNIT NO. 2 REFURBISHMENT AND TESTING OF THE REACTOR BUILDING POLAR CRANE AUXILIARY HOIST

1.0 Refurbishment of the Auxiliary Hoist

The Reactor Building Polar Crane's Auxiliary Hoist was damaged as a result of high temperatures experienced during the March 28, 1979 accident and subsequent environmental conditions. Pre-inspection assumptions based on experience gained during the refurbishment of the main hoist were that the damage would probably be concentrated in the crane's electrical system and that most mechanical components would only require lubrication, resurfacing or readjustment. These assumptions were later confirmed during auxiliary hoist inspections.

As a part of the auxiliary hoist refurbishment effort, the licensee performed mechanical and electrical walkdowns, performed electrical circuit and component checks, conducted a visual examination of the drum and brake components and inspected the block and the wire rope. A visual and non-destructive examination of the hook was also performed.



The most significant component replacements were the auxiliary hoist self actuated (SESA) brakes and the replacement of the wire rope. The licensee stated that the brakes and the wire rope were replaced in their entirety with "like-kind" components. However, there were numerous "unlike-kind" component replacements, most electrical in nature. In response to NRC questions on these replacements, GPUNC stated that most unlike-kind replacements were due to the unavailability of the exact part. All replacements were either functionally equivalent or conservatively affected the original component's operating characteristics (see discussion in Section 2.0).

The only component that was not refurbished was the hoist load sensing device on the trolley. In lieu of this part, load weight indication during the load test will be provided by a Dillon load cell included as a part of the rigging. (See Table 1.0 for a list of refurbished/ inspected components.) Based on the staff's review of refurbishment documents, we conclude that the auxiliary hoist for the reactor building polar crane was properly refurbished and is capable of performing a load test without adversely affecting public health and safety.

2.0 Unlike-Kind Component Replacements

In an NRC letter to the licensee dated February 14, 1985, the staff requested from GPUNC a complete list of "unlike-kind" component replacements. A portion of their response is included as Table 2.0.

-2-

It states that; (1) All unlike-kind replacements, except the weight type limit switch wire rope, were for electrical components. (2) The unlike-kind replacements that were not specifically recommended or approved by the vendor are functionally equivalent or superior. Based on information provided by the licensee, the staff concludes that the above referenced unlike-kind replacements are acceptable.

3.0 Load Test Components

The auxiliary hoist load test utilizes many identical components used during the reactor building polar crane main hoist test. All rigging below the missile shield rigging plate that will be used to lift the pressurizer missile shield during the auxiliary hoist load test is identical to that previously used to stage the missile shields for the polar crane main hoist load test. As illustrated in Figure 1.0, rigging components are composed of the 25 ton auxiliary hook, a 50 ton capacity Dillon load cell with an accuracy of + .5% and a factor of safety of five to ultimate: a Crosby anchor shackle with a factor of safety of six to ultimate; a missile shield rigging plate with a factor of safety of five to ultimate, plus an impact factor and additional design conservation to equal a reserve margin of 25% above the design load of 32.625 tons; four (4) 1 3/4" diameter, 6 x 37 class IWRC wire ropes with a minimum breaking strength of 153 tons each; four (4) 1 3/4" diameter screw pin anchor shackles each rated at 25 tons and the pressurizer missile shield and its associated lifting lugs.

-3-

It is anticipated that the missile shield will weigh approximately 32 tons and the associated rigging approximately 0.625 tons. The staff concurs with the design characteristics of the load test components.

4.0 Load Test Standards

The load test will be performed in accordance with ANSI B30.2 with some exceptions. Since the reactor building polar crane has previously been successfully load tested, the staff agrees with the licensee that a repeat of the trolley and bridging portion of that test is not required. The emphasis during the subject test is to verify the operability of the auxiliary hoist (no load test) and verify the load lifting capability (load test). The load lifting capability verification primarily involves testing the braking system. The staff concurs with the licensee's proposal to use ANSI B30.2 - 1983, paragraphs 2-2.2.2 as the basis for the load test with the bridging and trolleying maneuvers eliminated (2-2.2.2.b.2,3). As stated above, these capabilities have already been confirmed during the reactor building polar crane load test.

The staff also concurs with the licensee using ANSI B.30.2 - 1983, paragraphs 2-2.4.1 and 2-2.4.2 for wire rope inspection/replacement guidance in addition to the wire rope user's manual. Paragraphs 2-2.1.2a.4 and 2-2.3.3c.1 of ANSI B.30.2 - 1983 and paragraphs 10-1.4.2 and 10-1.4.6 of ANSI B30.10 - 1982 are appropriate as

-4-

proposed by GPUNC for hook inspections. The licensee has also committed to performing a magnetic particle inspection of the hook and inspecting the wire rope before and after the auxiliary hoist test.

It should be noted that the subject load test will be at approximately 32.6 tons or 130.5% of the rating of the auxiliary hoist (25 tons). ANSI B30.2 - 1983, paragraph 2-2.2.2a states that "Test loads shall not be more than 125 percent of the rated load, unless otherwise recommended by the manufacturer." The licensee has obtained the approval from Whiting Crane Co. to use a 32.6 ton test weight which is approximately 5.5% greater than that recommended in ANSI standards for a one time load test (see Attachment 1). The staff concurs with the above discussed exceptions to ANSI standards.

5.0 Quality Assurance/Quality Control

The TMI-2 Recovery Quality Classification List states that the polar crane's structure is the only Important-to-Safety (ITS) item on the crane. The staff agrees with the licensee that none of the refurbished auxiliary hoist components impact the polar crane's structural capabilities. However, the load test does exercise the crane's structure. Therefore, the test Unit Work Instruction (UWI) is labeled ITS. Even though refurbishment activities were labeled Not-Important-to-Safety (NITS) for the auxiliary hoist, Quality Assurance (QA) did witness some critical events such as the replacement of the auxiliary hoist brakes, the non-destructive examination of the auxiliary hoist hook, and reviewed many unlike-kind replacements. A

-5-

Quality Control (QC) receipt inspection is required for any replacement parts for the load bearing components.

Because of the ITS classification of the auxiliary hoist load test, QC will witness this test. There are also several QC Hold Points in the load test UWI to inspect or ensure that certain test parameters have been met.

6.0 Occupational Exposure

Based on information provided to the staff, GPU has estimated that the expected occupational exposure for the operational and load test will be between 7.5 to 22.5 person-rem. We consider GPU's estimate to be reasonable and conclude that the proposed activity and its potential environmental impacts are well within those previously assessed in the NRC's Programmatic Environmental Impact Statement (PEIS).

7.0 Load Drop Analysis and 50.59 Review

In a February 18, 1983 safety evaluation for the Polar Crane Load Test, GPUNC performed an analysis of the effects of dropping a missile shield in the areas being utilized for this load test. The staff reviewed that information and after obtaining additional information approved the licensee's safety evaluation on November 18, 1983. The load pathway and lift height restrictions for the auxiliary hoist load test are well within the bounds of the staff's previous analysis for the Polar Crane Load Test. Therefore, no additional analysis is required. See Figure 2.0 for the pressurizer missile shield pathway. Since the movement of the pressurizer missile shield, its pathway, and containment isolation will be consistent with what was previously approved by the staff in a November 18, 1983 letter, the 50.59 evaluation and conclusions presented by the licensee and approved by the staff in that letter are also applicable to the auxiliary hoist load test.

8.0 Load Test

The pressurizer missile shield will first be moved from the reactor building "A" D-ring by the polar crane main hook. After staging the shield at its load test position on the 347' elevation, the auxiliary hook will be rigged for the operational test. The no-load operational test will be performed to ensure that the control functions of the auxiliary hoist (including limit switch actuation) operate properly. The load test will then be conducted in accordance with ANSI B30.2 -1983 as previously stated per an NRC approved UWI. The load test incorporates individual brake tests to insure that both redundant trains are functioning properly. Following the load test, the pressurizer missile shield will be replaced on the "A" D-ring using the main hook. Containment integrity during the auxiliary hoist load test will be set at a level equal to that used during the previous polar crane test (e.g., containment purge, most non-borated water sources isolated, at least one personnel air lock door closed).

-7-

Pending the successful completion of the operational and load test of the auxiliary hoist and satisfactory hook and wire rope inspection results, the licensee will modify the Polar Crane Operating Procedure 4000-IMP-3891.01 to include the auxiliary hoist and present it to the staff for approval. The licensee is not permitted to use the auxiliary hoist for any load lifts before the NRC has concurred with a modification to the subject procedure.

Conclusion

Based on the above discussions, the staff concludes that:

- Pending the successful completion of the proposed Auxiliary Hoist (AH) operational test, the AH will be functionally ready for the load test.
- According to information provided by the licensee, all unlike-kind replacements were either recommended by the vendor, or functionally equivalent or functionally superior to the original component.
- The replacement of the wire rope was satisfactorily completed with a like-kind component.
- The inspection and maintenance plans for the AH are adequate to insure its safe use.

- 5. The planned load test sequence, not withstanding exceptions taken to ANSI certain standards, is sufficient to demonstrate the ability of the AH to lift 25 tons and be used throughout the TMI-2 cleanup.
- Quality assurance, quality control and procedural controls for the auxiliary hoist's refurbishment and requalification are sufficient to ensure the safe use of the hoist/crane and the safety of the planned test.
- 7. The likelihood of a load drop is extremely small and even if a drop did occur, the consequences of such an event are bounded by the staff's Safety Evaluation for the Refurbishment of the Reactor Building Polar Crane, Load Test and Recertification for Use dated November 18, 1983.
- The estimated occupational exposure for the load test is significantly
 less than that predicted by the staff's Supplement to the Programmatic Environmental Impact Statement dated October 1984.
- Based on the criteria contained in 10 CFR 50.59, the AH operational and load tests do not constitute an Unreviewed Safety Question.

Therefore, the Polar Crane Auxiliary Hoist Inspection and Refurbishment Plan and the load test safety evaluation is are acceptable as stated in our enclosed Safety Evaluation.

-9-

Table 1.0

POLAR CRANE AUXILIARY HOIST REFURBISHMENT PLAN

Component	Required	Remarks
Auxiliary Hoist Hain Drive Train		
Hoist Hotor	Yes	
Hoist Drive Hotor Resistors	Yes	
Motor Zero Speed Swithe	Yes	••
Coupling, Hoist Motor to Zero Speed Siwtch	Yes	
Flexible Couplings - Amerigear F-102	Yes	
Drive Gear Unit	Yes	
Driveshaft Support Bearings (2)	Yes	
All control components such as breakers, starters, switches & relays in Auxiliary Hoist Control Panel & Auxiliary Hoist Slow Speed Control Panel.	Yes	
All contractors (IA-4A), overload devices & fueses related to Auxiliary Hoist System	Yes	
xiliary Hoisting Unit		
Hoist Solenoid Brakes (2)	Yes	
Hoist Solenoid Drakes Rectifiers & Transformers	Yes	
Drum Support Bearing	Yes	
Hoist Wire Rope	Yes	
Hoist Weight Type Limit Switch	Yes	
Hoist Screw Type Limit Swithe	Yes	
Hoist Load Sensing Device on Trolley	No	
Adjustable Dial for Hoist Load Sensing Device		Load indication will be provided at load
Hoist Upper Sheave Nest	No	Since load sensing device on crane is not required
Hoist Bottom Block Assembly	Yes	
Hook	Yes	
	Yes	

POLAR CRANE AUXILIARY HOIST REFURBISHMENT PLAN

Component	Required	Remarks	
Auxiliary Hoist Inching Drive Train			
Drive Gear Motor	Yes		
Drive Hagnetic Clutch	Yes		
Drive Magnetic Clutch Rectifier & Transformer	Yes **		
Drive Eddy Current Orake	Yes		
Drive Eddy Current Brake Rectifier, Resistors & Transformers	Yes		
Flexible Coupling - Amerigear F-102	Yes		