

NRC

REV. 1  
DATE 5/2/79

EMERGENCY PROCEDURE EP- 19

TITLE: RC-112 Stack Shut

APPROVALS: PORC (Vice-Chairman) PI Warren DATE 5/3/79

WHIT SUBT: GA Rinder DATE 5/3/79

B&W OC Culman DATE 5/5/79 NRC MH Jette DATE 5/5/79

ALARA Edward Quora DATE 5-4-79

RC-V2 Stuck Shut1.0 Symptoms

1.1 When attempting to open

- a) No status light change
- b) No pressurizer pressure drop

1.2 Loss of BUS 2-32B indicated by loss of white power light for BUS 2-32.

2.0 Immediate Actions

2.1 Automatic Actions

None

2.2 Manual Actions

2.2.1 Manually control RCS pressure by:

Cycle pressurizer heaters to maintain pressure

2.2.2 If necessary, use RC-V-137 to relieve pressure

3.0 Follow Up Actions

3.1 If power to RC-V2 has been lost, energize alternate power supply per EP-7, Section 2.2.4.