

REV. 1
DATE 5/2/79

EMERGENCY PROCEDURE EP- 20

ARC

TITLE: RC-V137 Stack Shut

APPROVALS: PORC (Vice-Chairman) R. J. Warren DATE 5/3/79

UNIT SUPT: GA Hunter DATE 5/3/79

BSM BO R. Quinn DATE 5/5/79 HRC J. O. Hill DATE 5/5/79

ALARA Edna Quinn DATE 5-4-79

RC-V137 Stuck Shut

1.0 Symptoms

- 1.1 When attempting to Open - no status light change
- 1.2 When attempting to Open - no pressurizer pressure decrease
- 1.3 Loss of Bus 2-32B (loss of white power light for 2-32) disabling valve.

2.0 Immediate Actions

2.1 Automatic Actions

None

2.2 Manual Actions

2.2.1 Manually control pressurizer pressure by:

2.2.1.1 Cycle pressurizer heaters to maintain pressure.

2.2.1.2 If necessary, open RC-V2 to relieve pressure.

3.0 Follow Up Actions

- 3.1 If power to RC-V137 has been lost, energize alternate power supply per EP-7, Section 2.2.4.