4/17/79 NJA

ī.

TASKS REMAINING

€)

(

.

	Task	Lead Person	Expected Completion
1.	On-Line Boron Monitor/Criticality Protection Monitor	Ball	4/18/79
ż.	Diagnostics Recommendations for Unexpected Pump Trip	Ackermann	4/18/79
3.	Diagnostics Recommendations for Planned Switch to Natural Circulation	Schroeder	4/18/79
4.	Long-Term Diagnostics and Process Monitoring Recommendations through Plant Recovery, But Excluding Contaminated Cleanup	Schroeder	4/20/79
5.	Reactor Building Water Level Recommendations	Schroeder	4/20/79
6.	Reactor Core Water Level Coverage Confirmation in Natural Circulation	Schroeder	4/20/79
7.	Recommendations for Alternative P/V Control	Schroeder	4/21/79
8.	General Reviewing and Critiquing of Instrumentation and Monitoring Requirements and Implementation during TMI Recovery through Evolution to Natural Circulation	Ackermann Ball Schroeder	•• • •
9.	Overview of Thermocouple Strip Chart Recording	Zigler	4/18/79
10.	Recommendation on Alternatives for Pressurizer Level Indication	Schroeder	4/18/79

166 044

7905230457