

TASK CLOSE OUT DOCUMENT

Task Scope Provide recommendations
for alternative methods
of P/V control

To: M. Levenson
S. Levy
E. Zebroski

Task No. 2

Date Complete 5/7/79

Reason felt task is complete:

Task not complete IAG
broke up before completion of the
task.

Members of Committee

N. Ackerman

N. Ackerman / m. J. Lieb 5/7/79
Signed
Committee Leader